



**Glen-Gery
Iberia Plant
Iberia, OH**
Executive Summary
Project No. 2403-04

Two types of clay brick were submitted to AMT Laboratories by PROSOCO, Inc. with a request to determine the most appropriate new construction cleaner. Additionally, adverse effects testing on stain removal/maintenance cleaners suitable for clay brick were evaluated.

The laboratory report (2403-04 PTP Glen-Gery) provides information about the PROSOCO® products tested and descriptions of the test methods. The report includes test results as well as conclusions and recommendations. Recommendations are also provided in the chart below as indicated by an “x”.

Recommendations:

Sample	New Construction Cleaning		Specialty Cleaning					
	Sure Klean® 600 (1:6) or (1:8)	Sure Klean® Vana Trol® (1:6) or (1:8)	Sure Klean® Ferrous Stain Remover (1:3)	Sure Klean® 800 Stain Remover (1:1)	Sure Klean® White Scum Remover (1:1)	Sure Klean® ReVeal (1:3)	Sure Klean® Restoration Cleaner (1:3)	Enviro Klean® Klean 'N Release Cleaner (1:10)
“Colonial Rose” Facebrick	² ☒	¹ ☒	☒	☒	☒	☒	☒	☒
“Whiteford Range” Facebrick	² ☒	¹ ☒	☒	☒	☒	☒	☒	☒

NOTE: “1” indicates the recommended first choice and “2” indicates the recommended second choice. These recommendations are based on the Product Data Sheet limitations for certain brick types.

Apply all products in accordance with the manufacturer's recommendation provided on container labels and product data sheets. On-site testing should be conducted to determine the most appropriate product and procedures for a particular project. See product literature for additional application and product information.