



PROSOCO®

Sure Klean®

CLEANING & PROTECTIVE TREATMENTS

Iron Stain Remover

Sure Klean® Iron Stain Remover is a specialized product developed for removal of copper and other metallic salt staining from natural stone and masonry surfaces. A non-acidic poultice additive, Iron Stain Remover is safe for use on polished marble and other acid sensitive stone or masonry surfaces.

Iron Stain Remover is a clear liquid designed to be mixed with PROSOCO's Marble Poultice, an odorless non acidic blend of clays and biodegradable detergents in dry form. Properly prepared, the mixture produces a thick, creamy paste which is designed for trowel application to the stained surface.

REGULATORY COMPLIANCE

VOC Compliance

Sure Klean® Iron Stain Remover is compliant with all national, state and district VOC regulations.

TYPICAL TECHNICAL DATA

FORM	Clear, colorless liquid Ammonia odor
SPECIFIC GRAVITY	1.049
pH	9.0
WT/GAL	8.75 lbs
ACTIVE CONTENT	not applicable
TOTAL SOLIDS	not applicable
VOC CONTENT	not applicable
FLASH POINT	not applicable
FREEZE POINT	no data
SHELF LIFE	2 years in tightly sealed, unopened container

SAFETY INFORMATION

Always read full label and SDS for precautionary instructions before use. Use appropriate safety equipment and job-site controls during application and handling.

**24-Hour Emergency Information:
INFOTRAC at 800-535-5053**

Product Data Sheet

Sure Klean® Iron Stain Remover

PREPARATION

Protect foliage and painted surfaces by using polyethylene or other proven protective material. Avoid contact with auto and pedestrians by protecting or diverting such traffic.

Surface and Air Temperatures

Surface and air temperatures should be at least 50° F (10° C). Cold temperatures adversely affect the cleaning properties of Iron Stain Remover. Product should not be mixed or applied at temperatures below freezing. Wet poultice will freeze.

Equipment

Apply the prepared poultice mix using a plasterer's trowel or a wide, flexible taping knife.

Before the poultice dries, cover it with PROSOCO's OverCoat protective paper, glossy side down, and tape down the edges. OverCoat is a semi-impermeable protective paper for keeping poultice cleaners and paint removers moist, increasing effectiveness. The paper also protects cleaner and passersby from incidental contact. Visit www.prosoco.com or call 800-255-4255 for more information.

Storage and Handling

Transport and store in a cool, dry place with adequate ventilation. Always seal container after dispensing. Do not alter or mix with other chemicals. Published shelf life assumes upright storage of factory-sealed container in a dry place. Maintain temperatures of 45–100° F (7–38° C). Do not double stack pallets. Dispose of unused product and container in accordance with local, state and federal regulations.

APPLICATION

Read "Preparation" and the Safety Data Sheet before use.

ALWAYS TEST a small area of each surface to confirm suitability and desired results before beginning overall application. Test each type of masonry and each type of stain. Test with the same equipment, recommended surface preparation and application procedures planned for general application. Let test area dry 3–7 days before inspection and approval. Make the test panel available for comparison throughout the cleaning project.

Test at air and surface temperatures similar to those expected for overall cleaning. Temperature affects product performance.

Mixing

Iron Stain Remover should be mixed with PROSOCO's Marble Poultice to produce a thick creamy paste. Approximately 1 quart of Iron Stain Remover is required for each pound of dry Marble Poultice powder.

Mixing Procedures

1. Pour or shovel the dry Marble Poultice into a suitable mixing container.
2. While mixing, add sufficient Iron Stain Remover to produce a wet paste of a trowelable consistency.

Typical Coverage Rates

The prepared poultice mixture (1 quart of liquid/1 pound dry poultice powder) provides a coverage rate of approximately 4 square feet (0.37 square meters).

Application Instructions

1. Apply the prepared poultice mix to a uniform thickness of approximately 1/4 inch.
2. Cover the poultice with PROSOCO's OverCoat, glossy side down. Press the OverCoat protective paper against poultice. It will cling to the surface. Rub gently to remove air pockets and ensure smooth, overall adhesion. Tape/seal off edges of the film.
3. Allow the poultice to remain on the surface for 12–24 hours.
4. Remove OverCoat. Allow the poultice to dry completely, 2–4 hours. The poultice surface develops cracks as it contracts and dries. A fully developed network of cracks indicates the poultice is completely dry. Dry times may vary with environmental conditions such as temperature, wind and humidity.
5. After the poultice is completely dry, carefully scrape the poultice from the surface.
6. Using a stiff-fibered scrubbing brush and fresh water, wash the surface thoroughly removing all traces of the poultice paste.
7. Repeat poultice procedures where necessary.

Cleanup

Clean tools and equipment using fresh water.

Product Data Sheet

Sure Klean® Iron Stain Remover

WARRANTY

The information and recommendations made are based on our own research and the research of others, and are believed to be accurate. However, no guarantee of their accuracy is made because we cannot cover every possible application of our products, nor anticipate every variation encountered in masonry surfaces, job conditions and methods used. The purchasers shall make their own tests to determine the suitability of such products for a particular purpose.

PROSOCO, Inc. warrants this product to be free from defects. **Where permitted by law, PROSOCO makes no other warranties with respect to this product, express or implied, including without limitation the implied warranties of merchantability or fitness for particular purpose.** The purchaser shall be responsible to make his own tests to determine the suitability of this product for his particular purpose. PROSOCO's liability shall be limited in all events to supplying sufficient product to re-treat the specific areas to which defective product has been applied. Acceptance and use of

this product absolves PROSOCO from any other liability, from whatever source, including liability for incidental, consequential or resultant damages whether due to breach of warranty, negligence or strict liability. This warranty may not be modified or extended by representatives of PROSOCO, its distributors or dealers.

CUSTOMER CARE

Factory personnel are available for product, environment and job-safety assistance with no obligation. Call 800-255-4255 and ask for Customer Care – technical support.

Factory-trained representatives are established in principal cities throughout the continental United States. Call Customer Care at 800-255-4255, or visit our website at www.prosoco.com, for the name of the PROSOCO representative in your area.

