

Petersen Tegl Broager, Denmark Executive Summary Project No. 1905-05

Thirty-eight types of brick and three types of mortar were submitted to AMT Laboratories with a request to determine the most appropriate new construction cleaner. Additionally, stain removal products suitable for clay brick were evaluated for adverse effects.

The laboratory report (1905-05 PTP Petersen Tegl) provides information about the products tested and descriptions of the test methods. The report includes test results as well as conclusions and recommendations. Recommendations are also provided in the chart below.

## **Recommendations:**

Sample	New Construction Cleaning	Stain Removal (Adverse Effects)
"D20" Brick	MV Mangan Kontrol (1:6) OR MV Murvaerks Rens (1:1)	MV Rust Fjerner (1:1)
		OR MV Salt Fjerner (1:1)
"D23" Brick		MV Mangan Fjerner (1:3)
"D29" Brick		OR MV Bust Fierper (1:1)
		MV Rust Fjerner (1:1) OR
		MV Salt Fjerner (1:1)
"D31" Brick		MV Rust Fjerner (1:1)
		OR MV/ Solt Eigener (1:1)
		MV Salt Fjerner (1:1) MV Mangan Fjerner (1:3)
"D32" Brick		OR
"D33" Brick		MV Rust Fjerner (1:1)
"D34" Brick		OR MV Solt Eigener (1:1)
		MV Salt Fjerner (1:1)
"D35" Brick		
"D36" Brick		MV Rust Fjerner (1:1) OR
"D38" Brick		MV Salt Fjerner (1:1)
"D39A" Brick		

Apply all products in accordance with the manufacturer's recommendation provided on container labels and product data sheets. On-site testing should be conducted to determine the most appropriate product and procedures for a particular project. See product literature for additional application and product information.



Petersen Tegl Broager, Denmark Executive Summary Project No. 1905-05

**Recommendations: (cont.)** 

Sample	New Construction Cleaning	Stain Removal (Adverse Effects)
"D39B" Brick		MV Rust Fjerner (1:1)
"D42" Brick		OR MV Salt Fjerner (1:1)
		MV Mangan Fjerner (1:3)
"D43" Brick		OR
		MV Rust Fjerner (1:1)
		OR MV Salt Fjerner (1:1)
"D45" Brick		MV Rust Fjerner (1:1)
		OR
		MV Salt Fjerner (1:1)
"D46" Brick		MV Mangan Fjerner (1:3)
		OR MV Rust Fjerner (1:1)
	MV Mangan Kontrol (1:6)	OR
	OR MV Murvaerks Rens (1:1)	MV Salt Fjerner (1:1)
"D47" Brick		MV Rust Fjerner (1:1)
		OR
"D48" Brick		MV Salt Fjerner (1:1)
"D49" Brick		
"D51" Brick		MV Mangan Fjerner (1:3) OR
		MV Rust Fjerner (1:1)
"D54" Brick		OR
"D55" Brick		MV Salt Fjerner (1:1)
"D58" Brick		
"D70" Brick		MV Rust Fjerner (1:1)
		OR MV Oct Figure (4.4)
		MV Salt Fjerner (1:1)

Apply all products in accordance with the manufacturer's recommendation provided on container labels and product data sheets. On-site testing should be conducted to determine the most appropriate product and procedures for a particular project. See product literature for additional application and product information.



Petersen Tegl Broager, Denmark Executive Summary Project No. 1905-05

**Recommendations: (cont.)** 

Sample	New Construction Cleaning	Stain Removal (Adverse Effects)
"D71" Brick		MV Mangan Fjerner (1:3)
"D72" Brick		OR MV Rust Fjerner (1:1)
"D73" Brick	MV Mangan Kontrol (1:6)	OR MV Salt Fjerner (1:1)
"D76" Brick		MV Rust Fjerner (1:1)
"D78" Brick		OR MV Salt Fjerner (1:1)
"D81" Brick		MV Mangan Fjerner (1:3) OR MV Rust Fjerner (1:1) OR MV Salt Fjerner (1:1)
"D91" Brick		
"D92" Brick		
"D96" Brick	OR MV Murvaerks Rens (1:1)	
"D97" Brick		
"D98" Brick		
"D99" Brick		MV Rust Fjerner (1:1)
"D137" Brick		OR MV Salt Fjerner (1:1)
"D190" Brick		MV Mangan Fjerner (1:3) OR MV Rust Fjerner (1:1)
		OR MV Salt Fjerner (1:1)

Apply all products in accordance with the manufacturer's recommendation provided on container labels and product data sheets. On-site testing should be conducted to determine the most appropriate product and procedures for a particular project. See product literature for additional application and product information.